

FW Versior	Type	Subjects
B1.15	WiFi	Fix WiFi static network mask issue
B1.15	SOTI	Fixed SOTI Wi-Fi EAP certificates setting issue
B1.15	WiFi	Support WPA-WPA2 Mixed Mode for Enterprise
B1.15	TSPL	Add [TSPL] SET MENULOCK command
B1.15.14	BT	Support none MFi module.
B1.15.14	WiFi	Fixed the problem that EAP-Fast connection fail
B1.15.14	Menu	Add dump mode for imme EN on menu
B1.15.14	TSPL	Modify the Bluetooth MAC format
B1.15.24	SOTI	Fixed some SOTI bugs
B1.15.24	SOTI	Supported SOTI for Wi-Fi settings
B1.15.24	TSPL	Modify print quality setting command
B1.15.24	System	Fix hangup issue
B1.15.26	System	Modify delimiter to use ":" for MAC address
B1.15.26	RFID	Improve ZPL RFID command for hex format